### Characteristic features EN 1307



Name of article

Method of production ISO 2424

Width ISO 3018

Surface structure ISO 2424

Colourways

Pile material ISO 2424

Primary backing ISO 2424

Overall weight ISO 8543 Overall thickness ISO 1765

Pile service weight

Allure 1000

Tufted

ca. 400

Loop

Style

100% Econyl by Aquafil

**PES** 

ca. 2300 g/m<sup>2</sup>

ca. 7.0 mm

ca.  $1000 \text{ g/m}^2$ 

Secondary backing ISO 2424

Electrostatic loading ISO 6356

> 5

> 4

 $10^9 \Omega$ Surface resistivity ISO 10965 ROT

< 2 KV

Conductive action back

 $0.09 \, K^* m^2 / W$ Transparency to heat ISO 8302

Light fastness ISO 105-B02 Water fastness EN ISO 105 E01

Friction fastness EN ISO 105-X12 > 3-4

Stitch rate ISO 1763 ca. 130.700/m<sup>2</sup>



















EN 14041 | DOP: 1060 OC 3379 | NB: 1658













## **Health-promoting properties AIR**



- Free from PVC and bitumen.
- Free from formaldehyde.
- Reduction of fine dust in the breathing air.
- Free from harmful emissions and odors.
- TVOC limits are immediately met.
- Suitable for allergy sufferers



# **Health-promoting ACOUSTIC properties**



• Improved impact sound insulation +26dB Enhanced room acoustics  $+0.2\alpha_{\omega}$ 

Hz	125	250	500	1000	2000	4000
$\alpha_{\scriptscriptstyle S}$	0,00	0,05	0,10	0,35	0,45	0,50

- Increased employee concentration and motivation through enhanced well-being
- Acoustically effective







### **Environmental properties**

33FBBFC4



- Recycled primary backing
- Easy cleaning with water only





Made in Europe (production according to EU standard)

## **Product Information**

The staggered tufting process gives the loop quality a distinctive look. At the same time, the surface design gives the product typical properties in terms of delayed regeneration behavior. Indentations in the fibers recover after a short period of use.

### **Installation Instructions**

The seam is cut professionally from above inside the nap alley using a seam cutter, such as the one from Mittag. During this work process, it must be ensured that the nap alley is not left during cutting.

Data status 16.04.2024. Subject to changes due to technical advancements.